

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. 7,427,750B2
Patent Issue Date September 23, 2008
Application Serial No. 10/542187
Filing Date July 13, 2005
Assignee..... Griffin Analytical Technologies, LLC
Inventorship John W. Grossenbacher
Attorney's Docket No. GR61-042
Title: Mass Spectrometer Assemblies, Mass Spectrometry Vacuum Chamber
Lid Assemblies, and Mass Spectrometer Operational Methods

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR
APPLICANT MISTAKES AND PTO MISTAKES
(37 C.F.R. 1.322(a) and 1.323)

To: Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
ATTN: Decision and Certificate of Correction
Branch of the Patent Issue Division

From: Robert C. Hyta (Tel. 509-624-4276; Fax 509-838-3424)
Wells St. John P.S.
601 W. First Avenue, Suite 1300
Spokane, WA 99201-3828

Sir/Madam:

It is hereby requested that a Certificate of Correction be issued with respect to Patent No. 7,427,750B2, granted September 23, 2008, in accordance with the Certificate of Correction form attached hereto.

It is noted that Column 9, Line 65 in this patent of a typographical nature of character, as more fully described below. The error(s) occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination.

The other error(s) listed on the Certificate of Correction form were apparently incurred through the fault of the PTO as will be disclosed by the records of files in the Office.

Attached hereto, is Form PTO-1050, being suitable for printing.

The exact page and line number where the error occurs in the application file are:

Page 13, Line 6.

Please charge the \$100.00 fee specified under 37 C.F.R. § 1.20(a) to Deposit Account No. 23-0925. Please credit Deposit Account No. 23-0925 with any overpayment of the above fee.

Respectfully submitted,

Dated: 1/14/09.

By: 
Robert C. Hyta
Reg. No. 46,791

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,427,750B2

APPLICATION NO.: 10/542,187

DATED : September 23, 2008

INVENTOR(S) : Grossenbacher et al.

Patterson, Garth E.

It is certified that an error or errors appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 5, line 41, please delete "32-26" after "components" and insert --32-36--.

Col. 7, line 30, please delete "88" after "surface" and insert --86--.

Col. 8, line 17, please delete "canter" after "the" and insert --center--.

Col. 9, line 65, please delete "to" after "ther".

Mailing Address of Sender:

Robert C. Hyta
Wells St. John P.S.
601 West First Avenue, Suite 1300
Spokane, WA 99201-3828